

**Important Safety Recall Notice to Solo Customers**

Solo has issued a recall for model 441 battery operated backpack sprayers due to potential issues with battery overheating, possibly catching fire, smoking/scorching or bursting.



**Model(s) Involved:** 441

**Hazard:** Battery overheating & potentially catching fire, or bursting.

**Remedy:** Replace battery

Customers should immediately cease use of the recalled product, and contact Solo USA directly to obtain the replacement battery and further instructions.

**Consumer Contact:** Solo Inc. at 800-765-6462, or 757-245-4228 between 8:30am and 5:00pm ET Monday thru Friday. Email: [techserv@solousa.com](mailto:techserv@solousa.com)

**Recall Details:** Rechargeable batteries included with model 441 until 2021-02 manufacture date (see circled information on the batteries below) are affected by this recall.



**Old Version**



**New Version**

**Units Sold:** 1,486 in the United States, over 12,000 in Europe.

**Incidents/Injuries:** None yet reported in the US. Four cases of overheating batteries reported in Europe.

**Manufacturer:** Solo Inc.

**Manufactured in:** China