

Subject: Battery Connection

Models: 416-LI

Thank you for purchasing the model 416-LI. Your model 416-LI is shipped with the positive battery lead disconnected. Please see the instructions below to properly connect the battery. After completing the steps below your sprayer will need to be charged for 5 ½ hours. Please follow all other safety, operating, charging and maintenance information found in the operator's manual before operation.

1. Open front access cover.



2. Locate the positive battery lead (red wire) remove the insulation, either a yellow type as shown below, or a black heat shrink tubing will be found on some units covering the blade connector.



3. Securely insert the blade connector into the plug as shown below.



Solo Incorporated
5100 Chestnut Ave.
Newport News VA 23605
757-245-4228
800-296-7656 Toll Free Technical Services